

SAFETY ALERT 062310

Aircraft Operations without GRS Recovery System

ISSUED BY: TL-Ultralight s.r.o (TL).
Budova č.84 Letiště, 503 41
Hradec Králové, Czech Republic
Tel: +420 495 211 753
URL: www.tl-ultralight.cz

DATE OF NOTICE: 23 June 2010
EFFECTIVE DATE: Immediately
LIMITATIONS: None
AFFECTED AIRCRAFT: All TL-2000 and TL-3000 models
PAGES: This is page 1 of 1 pages.

REFERENCES: Previously issued GRS040609 Notice of Corrective Action by Galaxy High Technology, s.r.o (GRS); This TL Safety Alert 062310; The Aircraft Maintenance Manual (AMM); and the Aircraft Operation Instructions (AOI) / Pilot Operating Handbook (POH).

DISCUSSION: This Safety Alert establishes a procedure for the continued airworthiness of all SLSA certified TL-2000 or TL-3000 aircraft operations without an operational Galaxy Aircraft Recovery System.

TL Ultralight, s.r.o., recommends but does not require the GRS recovery system as minimum operating equipment. The aircraft may be operated with the recovery chute system out of service, provided the corrective action required below is taken.

DISTRIBUTION: Sent by mail to all aircraft owners on record. Sent by Certified Mail to each of the remaining owners on record affected by the GRS Notice 040609. This notice is also posted on the US distributor website: www.sting.aero/owner/notices.

CORRECTIVE ACTION: After expiration of the GRS system repack/revision date or an out of service condition, install the attached placard on the instrument panel in front of the right passenger seat. Enter in the aircraft log.

CONTINUED AIRWORTHINESS: Airworthiness of the aircraft is not affected by an out of service condition or expiration of the GRS system repack/revision date, provided this placard is properly placed in the aircraft.

Warning!

The service life of the aircraft
parachute system has expired.

The recovery system is not airworthy.

SCHEDULE: Comply with this notice immediately prior to the next flight upon an out of service condition or expiration of GRS system repack/revision date.

CONTACT: To receive another placard or to schedule an appointment for a GRS system replacement in the USA please contact the TL Ultralight distributor:

SportairUSA, LC
8222 Remount Road
North Little Rock, AR 72118
Phone 501.228.7777.
Fax 501.227.8888
Email: airworthiness@sportair.aero

End SA062310