

TL-ULTRALIGHT STINGSPOURT

How To Adjust The Trim Tabs

Trim tabs are located on the right aileron and the rudder of the TL 2000 StingSport. Adjusting one of the trim tabs is accomplished by bending the tab in the desired direction is a simple procedure, but should be done carefully to insure that the bend is uniform.

Bending the aileron trim tab is illustrated in the photo series below.

Small adjustments should be made, followed by flight testing. Repeat if necessary.



